

CODE ENFORCEMENT BOARD HEARING AGENDA

FEBRUARY 24, 2015 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FORT LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Howard Elfman, Chair • Chad Thilborger, Vice Chair • Joan Hinton

- Howard Nelson Paul Dooley Lakhi Mohnani Patrick McGee
- Joshua Miron (alternate) P J Espinal (alternate) Robert Smith (alternate)
- Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE13090364

CASE ADDR: 3001 N FEDERAL HWY
OWNER: MARQUEZ, ALICE
%NCDI REALTY CORP

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

SHEDS INSTALLED WITHOUT THE REQUIRED PERMITS OR

INSPECTIONS.

CASE NO: CE14011956

CASE ADDR: 1600 E LAS OLAS BLVD OWNER: WALTZER, RICHARD INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED WITH THE COMPLETION OF A WOOD PERGOLA WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH NEW OUTLETS AND SWITCHES UNDER THE PERGOLA WITHOUT

PERMITS.

CASE NO: CE14050074

CASE ADDR: 1545 NE 5 AV

OWNER: PETION, JUDE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.18

A FENCE WAS INSTALLED WITHOUT THE REQUIRED PERMIT

OR INSPECTIONS.

CASE NO: CE14051214
CASE ADDR: 814 NE 14 PL
OWNER: SE 14 CORP
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH AN ILLEGALLY BUILT LAUNDRY ROOM WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH AN ILLEGALLY BUILT LAUNDRY ROOM WITH PLUMBING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH AN ILLEGALLY BUILT LAUNDRY ROOM WITH ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

._____

CASE NO: CE14090227 CASE ADDR: 2885 NE 29 ST

OWNER: CONCAS, GERRARDO & VIOLETA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

CONSTRUCTION OF A NEW GAZEBO WITH A CONCRETE SLAB, CONCRETE COLUMNS, STEEL COLUMNS AND FRAMEWORK IS

BEING BUILT WITHOUT THE REQUIRED PERMIT OR

INSPECTIONS.

FBC(2010) 105.4.5

A NEW GAZEBO WITH ALL NEW ELECTRICAL IS BEING

INSTALLED WITHOUT THE REQUIRED PERMIT OR

INSPECTIONS.

CASE NO: CE14101811
CASE ADDR: 1504 NE 3 AV
OWNER: ROMAN, CARLOS V
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR REMODELLING WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14111158

CASE ADDR: 1611 NE 15 AV

OWNER: STEINER, JOSEPH G

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

CONSTRUCTION OF A PORCH STRUCTURE WITH OVERHANG WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE14111487 CASE ADDR: 1511 NE 17 AVE

OWNER: DURHAM, DUSTY KEITH

INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(b)

THERE ARE BUILDING PARTS WHICH ARE DETERIORATED

AND NOT MAINTAINED.

THE PROPERTY/BUILDING IS IN DISREPAIR WHICH

INCLUDES THE DETERIORATION AND FAILURE OF THE ROOF

TRUSSES AND PLYWOOD ROOF SHEATHING.

9-306

THE EXTERIOR BUILDING WALLS HAVE NOT BEEN MAINTAINED. STRUCTURAL PARTS INCLUDING FASCIA, SOFFITS AND BALCONIES HAVE LOOSE MATERIALS. THE PROPERTY/BUILDING IS IN DISREPAIR WHICH INCLUDES THE DETERIORATION AND FAILURE OF THE SOFFIT OVERHANG AT THE PERIMETER OF THE BUILDING.

9 - 308(A)

THE PROPERTY/BUILDING IS IN DISREPAIR WHICH INCLUDES THE DETERIORATION AND FAILURE OF THE ROOF TILE AND ROOF COVERING OF THE BUILDING.

FBC(2010) 110.9

THE PROPERTY OWNER NEEDS TO OBTAIN THE REQUIRED PERMITS AND MAKE THE NEEDED CORRECTIONS/REPAIRS WITHIN THE NEXT 30 DAYS. THESE PERMITS NEED TO BE OBTAINED, INSPECTED, PASSED AND CLOSED PRIOR TO THIS CODE CASE BEING COMPLIED AND CLOSED.

CASE NO: CE15010678

CASE ADDR: 2743 NE 15 ST # 8
OWNER: FALTINGS, JOHN

JONES, APHRODITE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELLING OF THE MASTER BATHROOM. THIS WORK INCLUDES BUT IS NOT LIMITED TO FRAMING, DRYWALL AND TILE BACKING BOARD BEING INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELLING OF THE MASTER BATHROOM. THIS WORK INCLUDES BUT IS NOT LIMITED TO ALL THE PLUMBING FIXTURES, SHOWER PAN, VALVES REPLACED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELLING OF THE MASTER BATHROOM. THIS WORK INCLUDES BUT IS NOT LIMITED TO REMOVING AND REPLACING THE ELECTRICAL DEVICES AND FIXTURES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT PROPERTY OWNER MUST HIRE A LICENSED CONTRACTOR TO OBTAIN ALL THE REQUIRED PERMITS, HAVE ALL OF THE REQUIRED INSPECTIONS SCHEDULE AND PASSED AND CLOSE ALL PERMITS IN ORDER FOR THIS CASE TO BE FULLY COMPLIED AND CLOSED.

CASE NO: CE15011806 CASE ADDR: 5160 NE 18 TER

OWNER: CARDINAL CAPITAL MANAGER LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE COMPLETE INTERIOR REMODELLING OF THE KITCHEN, TWO BATHROOMS, DRYWALL. TILE BACKING BOARD BEING INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF ALL THE PLUMBING FIXTURES IN THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF ELECTRICAL FIXTURES, DEVICES AND A SUB PANEL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF WINDOWS AND DOORS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE15010716

CASE ADDR: 2029 N OCEAN BLVD # 110 OWNER: MICHELIN, LUIGI & LORETTI

MICHELIN, PAULA & PIETROBON, NADIA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELLING OF ONE FULL BATHROOM AND A PARTIAL REMODELLING OF THE KITCHEN. THIS WORK INCLUDES BUT IS NOT LIMITED TO STRUCTURAL FRAMING, DRYWALL AND TILE BACKING BOARD INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELLING OF ONE FULL BATHROOM THAT INCLUDES THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES INCLUDING A NEW SHOWER PAN. THIS PLUMBING WORK WAS PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE ELECTRICAL DEVICE IN THE BATHROOM. THE KITCHEN ELECTRICAL HAS BEEN ALTERED WITH THE RELOCATION OF ELECTRICAL DEVICE, JUNCTION BOX AND FIXTURES. THIS ELECTRICAL WORK WAS PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

PROPERTY OWNER NEEDS TO OBTAIN ALL THE REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, AND HAVE ALL PERMITS PROPERLY CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15011828

CASE ADDR: 2029 N OCEAN BLVD # 410

OWNER: BLAYLOCK, R MARK INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELLING OF TWO FULL BATHROOMS AND A COMPLETE REMODELLING OF THE KITCHEN. THIS WORK INCLUDES BUT IS NOT LIMITED TO STRUCTURAL FRAMING, DRYWALL AND TILE BACKING BOARD INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELLING OF TWO FULL BATHROOMS AND THE KITCHEN THAT INCLUDES THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES INCLUDING A NEW SHOWER PANS. THIS PLUMBING WORK WAS PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE ELECTRICAL DEVICE IN THE BATHROOMS AND KITCHEN. THE KITCHEN ELECTRICAL HAS BEEN ALTERED WITH THE RELOCATION OF ELECTRICAL DEVICE, JUNCTION BOX AND FIXTURES. THIS ELECTRICAL WORK WAS PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

PROPERTY OWNER NEEDS TO OBTAIN ALL THE REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, AND HAVE ALL PERMITS PROPERLY CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE13110620

CASE ADDR: 1123 W LAS OLAS BLVD

OWNER: WHALEN, SUZANNE INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.18

A WOOD FENCE HAS BEEN INSTALLED ON THE PROPERTY

WITHOUT A PERMIT.

CASE NO: CE14102297
CASE ADDR: 1211 NE 2 AVE

OWNER: NICHOLS, CHARLES A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

EXTENSIVE WORK HAS BEEN DONE ON THIS DUPLEX, WITHOUT ANY PERMITS. WORK INCLUDES BUT IS NOT

- 1. INTERIOR RENOVATIONS IN PROGRESS INSIDE BOTH UNIT BATHROOMS AND KITCHENS, WITH NEW PLUMBING AND ELECTRICAL FIXTURES.
- 2. NEW LAUNDRY ROOM WAS BUILT.
- 3. THE OPENINGS PROTECTIONS WERE REPLACED ON BOTH SIDES OF THE DWELLING.
- 4. TWO DUCTED CENTRAL A/C SYSTEMS WERE INSTALLED.
- 5. A WOOD FENCE WAS INTALLED AROUND THE PROPERTY LOT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110356

CASE ADDR: 2612 BARBARA DR MONDANI, GLEN H/E MONDANI, PENTELOPE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REOUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT.

STOP WORK ISSUED.

THERE IS WORK IN PROGRESS WITH EXPIRED PERMITS: 1. COMPLETED RENOVATION INSIDE OF THE DWELLING.

- 2. AN ELECTRICAL GENERATOR WITH GAS OR LP SUPPLIED TO IT WAS INSTALLED. THREE GAS SUPPLY LINES RAN TO THE INTERIOR OF THE HOUSE.
- 3. THE GARAGE WAS DEMOLISHED AND A SERVANT'S QUARTERS WAS BUILT WITH ELECTRICAL AND PLUMBING ALTERATIONS.
- 4. HURRICAINE SHUTTERS WERE INSTALLED.
- 5. AN EXTERIOR DOOR WAS REPLACED.
- 6. ALTERATIONS TO THE FRONT PORCH.
- 7. PAVERS IN THE DRIVEWAY WERE DONE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CE14051438 CASE NO: CASE ADDR: 645 NW 14 TER

OWNER: 645 NW 14 TERRACE LANDTRUST

SWITZER, STAN TRSTEE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS, AS FOLLOWS:

1. THIS PROPERTY WAS UPGRADED. THE INTERIOR WAS REMODELED WITH NEW CABINETS INSTALLED IN THE

KITCHEN AND BATHROOM AREAS.

2. NEW ELECTRICAL AND PLUMBING FIXTURES ALSO WERE INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14061177 CASE ADDR: 3505 SW 12 CT

OWNER: MCFARLANE, CHRISTINE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY:

- 1. THE GARAGE OR CARPORT WAS ENCLOSED INTO LIVING SPACE WITHOUT A C.O.
- 2. THE WINDOWS IN THE DWELLINGS' OPENINGS WERE REPLACED.
- 3. THE KITCHEN AND BATHROOM WERE UPGRADED WITH NEW PLUMBING AND ELECTRICAL FIXTURES.
- 4. NEW CABINETRY WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14072224

CASE ADDR: 3621 SW 22 ST

OWNER: MARTIN, IDANIA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. THE OWNERS OF THIS PROPERTY HAVE REMOVED A CHAIN LINK FENCE BELONGING TO 3620 SW 21 CT AND REPLACED IT WITH A WOOD FENCE.
- 2. THEY BUILT A SHED TO HOUSE LARGE DOGS AND IS ATTACHED TO THE WOODEN FENCE.
- 3. BETWEEN 2007 AND 2008 A STORAGE SHED WAS INSTALLED.
- 4. BETWEEN 2011 AND 2012 A SLAB ON GRADE WAS DONE ON THE WEST SIDE OF THE PROPERTY LOT.
- 5. IN 2012, WOOD FENCES WITH GATES WERE ERECTED ON BOTH SIDES OF THE PROPERTY FRONT FACING SOUTH.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14080757

CASE ADDR: 1609 NW 12 ST

OWNER: GILA ROZEN LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS AS FOLLOWS:

1. THE WINDOWS WERE REPLACED ON ALL THE OPENINGS AT THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR
OWNER: WSC BRICKELL LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14081062
CASE ADDR: 1512 NW 18 CT
OWNER: SB TRS LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. THE WINDOWS AND DOORS WERE REPLACED AT THE DWELLING.
- 2. ALTERATIONS OF THE INTERIOR INSIDE THE KITCHEN AND BATHROOMS.
- 3. THERE ARE NO NEW PERMITS SEEN ON CITY RECORDS SINCE 2008.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14101891

CASE ADDR: 749 W DAYTON CIR

OWNER: 2013B PROPERTY OWNER LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT STOP WORK ISSUED

- 1. THE INTERIOR OF THE PROPERTY IS BEING GUTTED.
- 2. PLUMBING, ELECTRICAL AND STRUCTURAL WORK IS IN PROGRESS.
- 3. THE BATHROOMS AND KITCHEN ARE BEING ALTERED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 115.1

STOP WORK ORDER

ALL WORK IN PROGRESS MUST BE STOPPED UNTIL ALL

REQUIRED PERMITS ARE ISSUED.

CASE NO: CE14110452 CASE ADDR: 1729 NW 16 AVE

OWNER: CUKIERKORN, JACQUES

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT. STOP WORK ISSUED

- 1. INTERIOR ALTERATIONS IN THE KITCHEN AND BATHROOM AREAS. BOTH WERE GUTTED.
- 2. FRAME AND DRYWALL WORK BEING DONE WITH NEW PLUMBING AND ELECTRIC FIXTURES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE08070448 CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

- 1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.
- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE10070711 CASE ADDR: 2601 SW 13 PL

OWNER: VEGA, GLORIA STELLA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS FOR WORK IN PROGRESS:

- 1. INSTALLING WOOD FENCE.
- 2. REBUILDING FRONT WITH PORCH (ROOF) OVERHANG.
- 3. WOOD SIDING WORK AT THE REAR OF THE DWELLING AND STRUCTURAL WORK AROUND THE WINDOWS.
- 4. THIS DWELLING WAS DAMAGED BY A FIRE ON SEPTEMBER 30, 2002 AS PER CASE CE02100033. THERE ARE NO PERMITS ON RECORD TO PERFORM AND RESTORE WORK AFTER THE FIRE.

FBC(2007) 109.10

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE11110991 CASE ADDR: 2845 SW 4 ST

OWNER: GALLINGTON, MARILYN K

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT. 1. NEW WINDOWS WERE INSTALLED AND THERE ARE TWO DISTINCT ADDITIONS IN THE REAR PER BCPA INSPECTOR

GREG FRITZ'S E-MAIL:

WE FOUND SCREEN ENCL. REMOVED & BLOCKED UP W/CBS & WIN-DOWS, ADDED ANOTHER ROOM W/POWER METER INSIDE THIS NEW ROOM, CLOTHES DRYER DRAINING ON LAWN, NEW WATER HEATER, ROMEX IN LAUNDRY RM, NEW A/C UNIT NEW ELECT. TO BOTH ILLEGAL ADDITIONS, ASPHALTED A CIRCULAR DRIVE ON THE FRONT. - G.F.

FBC(2007) 109.10

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13021763

CASE ADDR: 1200 CITRUS ISLE OWNER: LAZARIDI, ALLEN INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED BY A REMODELING PROJECT THAT INCLUDES BUT IS NOT LIMITED TO THE FOLLOWING WORK WITHOUT A PERMIT:

1. CARPORT ENCLOSED.

2. NEW WINDOWS HAVE BEEN INSTALLED.

3. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.

4. NEEDS PERMIT FOR ELECTRICAL WORK TO THE DOCK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13071954 CASE ADDR: 1217 NW 18 AV

OWNER: BENTLEY, LEON & EASTER

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS, AND CERTIFICATE OF OCCUPANCY

FROM THE CITY BUILDING DEPARTMENT:

1. THE CARPORT WAS ENCLOSED INTO A LIVING SPACE WITH A BATHROOM INSIDE.

2. A CENTRAL A/C HAS BEEN INSTALLED INSIDE THE DWELLING.

CASE NO: CE13100827
CASE ADDR: 1609 NW 11 ST
OWNER: SCOTT, DONALD H/E

HYDE, MARY LEE & SCOTT, JOSEPH

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. INTERIOR RENOVATIONS IN PROGRESS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13101928
CASE ADDR: 2201 NW 23 LN
OWNER: MCGILL, SHERRI
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

THIS COMPLAINT CAME FROM FLFD. THIS SINGLE FAMILY DWELLING WAS DAMAGED BY A FIRE AS REPORTED TO US BY THE FIRE MARSHALL'S OFFICE.

- 1. FRAMING AND DRYWALL WORK WAS DONE TO REPAIR THE DAMAGED INTERIOR OF THE DWELLING.
- 2. WINDOWS WERE REPLACED. THE OUTSIDE WALL WAS REPAIRED AROUND THE OPENINGS.
- 3. THE DAMAGED ROOF DECK WAS REPAIRED OR REROOFED.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13111632
CASE ADDR: 335 SW 18 AVE
NEW OWNER: SOFREI LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED WITH BATHROOM RENOVATIONS WITHOUT A PERMIT.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE COMPLETION OF THE BATHROOM RENOVATIONS WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED BY THE COMPLETION OF THE BATHROOM RENOVATIONS WITHOUT A PERMIT.

FBC(2010) 1604.1

THE CARPORT ROOF STRUCTURE HAS DETERIORATED TO THE POINT THAT IT DOES NOT MEET GRAVITY LOADING THAT IT WAS ORIGINALLY DESIGNED TO MEET.(CMP)

TI WID ORTGINALLI DIBIONID TO MELLI. (CM.)

CASE NO: CE14022025 CASE ADDR: 619 SW 20 TER

OWNER: FIVE TEN FLORIDA IV LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT PERMITS:

- 1. COMPLETED KITCHEN REMODELING.
- 2. COMPLETED BATHROOM REMODELING.
- 3. ENCLOSED CARPORT.
- 4. NEW WINDOW INSTALLATIONS.
- 5. REMOVAL OF INTERIOR WALLS

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE COMPLETION OF KITCHEN AND BATHROOM RENOVATIONS WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE COMPLETION OF THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.11

THE A/C SYSTEM HAS BEEN ALTERED WITH THE INSTALLATION OF EQUIPMENT AND DUCT WORK WITHOUT A PERMIT.

CASE NO: CE14031651
CASE ADDR: 937 NW 13 ST
OWNER: LEVY, JEFFREY B
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. THERE ARE MAJOR RENOVATIONS GOING ON AT THIS PROPERTY INCLUDING THE FOUNDATION REPAIRS IN THE REAR OF THE HOUSE.
- 2. A ROOM ADDITION IS ALSO BEING BUILT ON THE REAR OF THE BUILDING.
- 3. IN THE VERY REAR OF THE PROPERTY LOT A SHED WAS BUILT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14032296
CASE ADDR: 516 SW 16 ST
OWNER: THIER, JASON
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AND THE REQUIRED C.O. FROM THE CITY OF FORT LAUDERDALE:

- 1. THIS MULTI-FAMILY DWELLING HAS BEEN EXPANDED ALL THE WAY TO THE REAR SETBACK OF THE PROPERTY OR THE SOUTH SIDE AND TO THE WEST SET BACK.
- 2. A LARGE WOOD STRUCTURE WAS BUILT.
- 3. A STORAGE SHED WAS INSTALLED.
- 4. A WOOD FENCE WAS ERECTED AROUND THE BACK OF THE PROPERTY LOT WITH A DOUBLE GATE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14051355
CASE ADDR: 3051 NW 23 ST
OWNER: WILLIAMS, THERESA
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. A SHED IN THE BACK YARD WAS ADDED TO THE HOUSE IN THE REAR BY THE POOL.

- 2. A WOOD FENCE WAS ERECTED BEHIND THE DWELLING. ALL WORK WAS PERFORMED IN 2011.
- 3. THE DWELLING WAS REROOFED WITH SHINGLES ON APRIL 19, 2006. THE ISSUED PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING THE FINAL. TODAY IT REMAINS WORK WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14051500 CASE ADDR: 1389 SW 24 AVE

OWNER: FIVE TEN FLORIDA III LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

A NEW CASE HAS BEEN OPENED; SOME OF THE VIOLATIONS

WERE REMOVED

1. THE WINDOWS AND DOORS REMAIN WITHOUT $\ensuremath{\mathtt{A}}$

PERMIT.

2. THE CENTRAL A/C WAS REPLACED.

3. THE KITCHEN AND THE BATHROOMS WERE UPGRADED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14030884
CASE ADDR: 1213 NW 23 TER
OWNER: THOMAS, BETHANI J
WILLIAMS, KIMBERLY

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. INTERIOR REMODELING WAS DONE IN THE BATHROOMS(2) AND KITCHEN. PERMIT HISTORY SHOWS ONLY ONE BATHROOM WAS BUILT WITH PERMIT. THERE ARE TWO EXISTING AND BOTH WERE REMODELLED.

2. IN THE LAUNDRY ROOM A NEW WASHER & DRYER

HOOK-UP WAS INSTALLED.

3. THE EXISTING WATER HEATER WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14060438
CASE ADDR: 930 NW 14 ST

OWNER: ADEA REAL ESTATE LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM IS FAULTY. THE FUSE BOX IS

SPARKING. THERE ARE AREAS WITHOUT POWER. A

CABINET WAS INSTALLED ON FRONT AND IT IS COVERING THE FUSES. IT COULD NOT BE REACHED IN CASE OF AN

EMERGENCY. IT HAS BECOME AN ELECTRICAL FIRE

HAZARD.

CASE NO: CE14060528 CASE ADDR: 1213 NW 3 ST

OWNER: TOTAL HOUSING INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AND THE REQUIRED C.O. FROM THE CITY OF FORT LAUDERDALE.

- 1. THE CARPORT HAS BEEN ENCLOSED AND A BATHROOM WAS ADDED TO IT.
- 2. THE DWELLING HAS BEEN CONVERTED FROM A SINGLE FAMILY TO MULTI-FAMILY OR DUPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A MULTI-FAMILY DWELLING WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE14071821 CASE ADDR: 1070 NW 25 AV

OWNER: LANDERS, MARIE H/E

TAYLOR, MARTHA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. SRT WORK DONE WITHOUT PERMITS. THIS PROPERTY HAS BEEN ALTERED BY THE OWNER ENCLOSING THE OPEN PORCH ON THE SOUTH SIDE OF THE DWELLING. IT IS BEING USED AS LIVING SPACE.(CMP)
- 2. THE WINDOWS WERE REPLACED IN THE OPENINGS.
- 3. STORAGE SHED WAS INSTALLED AT THE REAR OF THE DWELLING. 4. IN ADDITION, THE PROPERTY OWNER IS RENTING OUT ROOMS, INCLUDING THE ENCLOSED PORCH.

FBC(2010) 105.1.5

THE OWNERS ARE SELLING PREPARED FOOD TO THE PASSING PUBLIC FROM THE CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 1604.1

THE STRUCTURES FOR THE ROOF AND WALLS BELONGING TO THE SOUTH SIDE ENCLOSED PORCH DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALSO, THE ADDITION ON THE EAST SIDE OF THE BUILDING WHICH HOUSES A WATER HEATER IS NOT BUILT STRONG ENOUGH TO RESIST THE WIND AND GRAVITY LOADS THAT MAY BE IMPOSED. THE CONSTRUCTION METHODS AND MATERIALS DO NOT CONFORM TO ANY CODE.

ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AS PER FBC 116.1.2 AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO THE WIND'S UPLIFT.

CASE NO: CE13030518

CASE ADDR: 1215 SEMINOLE DR OWNER: KEENAN, BRIAN F INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR REMODELING WITHOUT PERMITS.

CE13041247 CASE NO:

CASE ADDR: 124 HENDRICKS ISLE SIDMAN, HUE KIM OWNER: INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THE PARKING LOT HAS BEEN ALTERED BY A SEAL COAT

AND RESTRIPING PROJECT WITHOUT A PERMIT.

CASE NO: CE13060564 CASE ADDR: 1339 NE 14 AVE OWNER: CHAI LV LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

WORK BEING DONE WITHOUT THE REQUIRED PERMITS:

- 1. REPLACED WINDOWS. 2. ENCLOSED CARPORT. 3. REPLACED A.C. UNIT.
- 4. UPGRADED ELECTRICAL SERVICE. 5. REPLACING PLUMBING FIXTURES.

FBC(2010) 105.4.4

REPLACING SINKS AND PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS.

FBC(2010) 105.4.5

UPGRADED THE ELECTRICAL SERVICE PANEL WITHOUT THE REQUIRED PERMITS.

FBC(2010) 105.4.11

REPLACED AIR CONDITIONING UNIT WITHOUT THE REQUIRED PERMIT.

FBC(2010) 105.4.15

REPLACING WINDOWS AND DOORS WITHOUT THE REQUIRED

PERMITS.

CASE NO: CE13091177 CASE ADDR: 3210 NW 63 ST

OWNER: STYCZYNSKY, RANDALL W

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

1. REPLACING WINDOWS AND DOORS.

2. ALTERING OPENING FROM WINDOWS TO DOORS, WHICH INCLUDES FILLED CELLS AND ELECTRICAL WORK.

ALL WORK DONE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

FBC(2010) 105.4.5

ADDING ELECTRICAL WIRING, ELECTRICAL BOXES, AND FUTURE FIXTURES WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

REPLACING WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 1604.1

ALTERING EXTERIOR OPENINGS FOR BOTH WINDOWS AND DOORS THAT INCLUDES FILLED CELLS, BLOCK, POURED SILLS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

CASE NO: CE14060539

CASE ADDR: 2496 CAT CAY LN

OWNER: 1463 PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR DEMOLITIONS AND REMODELING WORK TAKING PLACE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

A STOP WORK ORDER WAS PLACED ON THE JOBSITE.

CASE NO: CE14071427 CASE ADDR: 1501 NE 12 ST

OWNER: POLARIS GV INVESTMENTS LLC

% MONICA VACAS

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE ARE ALTERATIONS BEING DONE TO THIS BUILDING WITHOUT THE REQUIRED PERMITS OR INSPECTIONS. THE FRONT OF THE BUILDING HAS HAD ALTERATION DONE TO THE BEAM AND CEILING.

FBC(2010) 105.4.1

A CONCRETE SLAB WITH A STORAGE SHED HAS BEEN BUILT WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

FBC(2010) 105.4.11

THE A/C UNITS HAVE BEEN REPLACED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

THE WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

FBC(2010) 105.4.5

THE ELECTRICAL TO THIS BUILDING HAS BEEN ALTERED. THERE IS NEW ELECTRICAL LINES AND DISCONNECT BOXES TO THE A/C UNITS. THERE IS ALSO NEWER ELECTRICAL CONDUIT INSTALLED ON THE OUTSIDE CORNER OF THE BUILDING.

CASE NO: CE14082172

CASE ADDR: 2200 S OCEAN LA # 910

OWNER: BUTTERFIELD LTD INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED. A WALL IN THE KITCHEN HAS BEEN REBUILT WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS. THIS WALL ALSO NOW ENCROACHES INTO UNIT 909 KITCHEN SPACE. THIS WALL NEEDS TO BE REVERTED BACK TO THE ORIGINAL LAYOUT.

CASE NO: CE14090039 CASE ADDR: 3145 NE 9 ST

OWNER: ESPOSITO ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS COMMERCIAL BUILDING HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE

REQUIRED PERMITS OR INSPECTIONS.

CASE NO: CE14100097

CASE ADDR: 1180 N FEDERAL HWY OWNER: PREMIER RIVA LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE IS A TWO STORY SCAFFOLD SET UP THAT IS THE

STRUCTURAL SUPPORT FOR THE BANNER

ADVERTISING/PROMOTION THAT WAS ERECTED WITHOUT THE

REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.7

- 1. THERE ARE TWO NEW SIGNS AT THE ENTRANCE TO THIS SITE THAT HAVE BEEN INSTALLED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THERE ARE LARGE BANNERS THAT ADVERTISE AND PROMOTE THE FUTURE CONDO THAT WERE ERECTED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THERE ARE AWNINGS THAT WERE INSTALLED ON THE SALES TRAILER OFFICE THAT WERE INSTALLED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

CASE NO: CE14071289

CASE ADDR: 1920 S OCEAN DR # 1207 JOHN MACDONALD LIV TR

MACDONALD, JOHN H TRSTEE

INSPECTOR: ROBERT MASULA

FBC(2010) 105.1

THE KITCHEN AND BATHROOM ARE BEING REMODELED WITHOUT THE REOUIRED PERMITS AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT LIMITED TO FRAMING AND DRYWALL.

FBC(2010) 105.4.3

THE KITCHEN CABINETS, ELECTRICAL, PLUMBING, DRYWALL HAVE BEEN DEMOLISHEDED AND REMOVED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THE KITCHEN AND BATHROOM ARE BEING REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT LIMITED TO PLUMBING WORK AND REMOVING AND REPLACING FIXTURES.

FBC(2010) 105.4.5

THE KITCHEN AND BATHROOM ARE BEING REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT LIMITED TO ELECTRICAL WORK, EXPOSED CONDUIT THAT IS NOT SECURED, REMOVING AND REPLACING FIXTURES AND DEVICES.

CE14051629 CASE NO: CASE ADDR: 1338 NW 7 PL

OWNER: MCCLOVER, ULYSSES & EVELYN

INSPECTOR: LEROY JONES

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. A LARGE STORAGE BUILDING HAS BEEN INSTALLED AT THE FRONT OF THE PROPERTY.
- 2. A WOOD FENCE WAS ERECTED AROUND THE PROPERTY LINE.
- 3. A NEW DRIVEWAY WAS BUILT AT THE REAR ALL THE WAY TO THE MAIN STREET.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE14062184
CASE ADDR: 517 NW 7 AVE

OWNER: SOUTHERN REO GROUP LLC

INSPECTOR: LEROY JONES

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND CERTIFICATE OF OCCUPANCY

FROM THE CITY BUILDING DEPARTMENT. A STOP WORK ORDER WAS ISSUED FOR:

- 1. WORK IS IN PROGRESS. THE INTERIOR IS BEING REMODELED.
- 2. UPGRADING THE ELECTRICAL, PLUMBING AND THE MECHANICAL SYSTEMS.
- 3. NEW FRAMING AND DRYWALL IN PROGRESS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14021595 CASE ADDR: 1842 NE 26 AV

OWNER: AILOS, MORDECHAI M

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THE SECOND FLOOR WOOD BALCONY HAS BEEN REMOVED AND WILL BE REPLACED IN THE NEAR FUTURE.
- 2. THE EXTERIOR SIDING ON THE SECOND FLOOR, ON THE BACK SIDE OF THIS TOWNHOUSE HAS BEEN REMOVED, BLACK ROLL UNDERLAYMENT HAS BEEN INSTALLED.
- 3. A PATIO SLAB IS BEING FORMED AT THE GROUND LEVEL FOR A FUTURE CONCRETE OR PATIO DECK.
- 4. A FENCE HAS BEEN INSTALLED ALONG THE BACK SIDE OF THIS TOWNHOUSE.

ALL OF THIS WORK IS BEING DONE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

CASE NO: CE13050613 CASE ADDR: 1433 SW 33 CT

OWNER: FEDERAL NATIONAL MORTGAGE ASSN % ON

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS AS FOLLOWS:

1. THE WINDOWS AND THREE DUCTED CENTRAL A/C'S AT THIS MULTI-FAMILY DWELLING WERE REPLACED. THERE

ARE NO PERMITS ON RECORD FOR THAT WORK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13120935 CASE ADDR: 1133 SW 5 PL

OWNER: COOK, KAMERIN PARTIN, JOEY

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE INSTALLATION OF WATER SUPPLY AND WASTE LINES FOR A WASHING MACHINE WITH A VOIDED PERMIT AND IS NOW WORK WITHOUT PERMITS.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE INSTALLATION OF OUTLETS FOR A WASHING MACHINE AND ELECTRIC DRYER WITH A VOIDED PERMIT AND IS NOW

WORK WITHOUT PERMITS.

CASE NO: CE14021929 CASE ADDR: 3000 SW 4 AVE

OWNER: CELLULAR SUPPLIES REAL ESTATE INC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE COMMERCIAL BUILDING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT A PERMIT:

1. INTERIOR PARTITIONS HAVE BEEN ADDED AND ALTERED.

- 2. AN ALUMINUM PAN ROOF AND STRUCTURE WAS ADDED TO THE REAR.
- 3. A CONCRETE FLOOR HAS BEEN RAISED.
- 4. A KITCHEN RENOVATION HAS BEEN COMPLETED.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED WITH THE COMPLETION OF A KITCHEN RENOVATION WITHOUT A PERMIT.(CMP)

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE ADDITION OF VARIOUS OUTLETS, SWITCHES, AND LIGHTING WITHOUT A PERMIT.

FBC(2010) 105.4.11

THE A/C SYSTEM IN THE COMMERCIAL BUILDING HAS BEEN WITHOUT A PERMIT.

CASE NO: CE13121503 CASE ADDR: 1360 SW 32 ST

OWNER: LARA, JOSE A & MARIA T

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.4.13

A SWIMMING POOL HAS BEEN COMPLETED ON THE PROPERTY

WITHOUT A PERMIT.

FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED WITH THE ADDITION OF AN OVERHANG ON THE SIDE OF THE HOUSE AND A FENCE INSTALLED AROUND THE POOL

WITHOUT PERMITS.